

## LIST OF VEHICLES TO BE DISPOSED OFF

#	REGISTRATION #	MAKE & MODEL	PRODUCT	AGE	DOMETER READIN	CONDITION	CONDITION	
							INTERNAL	EXTERNAL
1	GGW895EC	VW POLO VIVO 1.6 SEDAN	MM	6	212 059	Uneconomic to maintain due to age	GOOD	WHEELCAPS - RIM
2	GGW731EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	87 656	Uneconomic to maintain due to age	GOOD	HEAD LIGHTS NOT FITTED
3	GGW870EC	VW POLO VIVO 1.6 SEDAN	MM	6	196 187	Uneconomic to maintain due to age	FAIR	CHIP IN THE MIRROR, DENT DOOR FRONT, DENT PLATE REGISTRATION AND MIRROR & BUMPER
4	GGW873EC	VW POLO VIVO 1.6 SEDAN	MM	6	176 637	Uneconomic to maintain due to age	GOOD	DENT ON FRONT BUMPER & CHIPS LEFT & RIGHT SIDE
5	GGW322EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	146 955	Uneconomic to maintain due to age	GOOD	ROLLER BAR BROKEN
6	GGW891EC	VW POLO VIVO 1.6 SEDAN	MM	6	167 551	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
7	GGW892EC	VW POLO VIVO 1.6 SEDAN	MM	6	168 104	Uneconomic to maintain due to age	GOOD	NO TRIANGLE
8	GGW737EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	99 353	Uneconomic to maintain due to age	FAIR	NO WHEEL SPANNER, SCRATCHES ON LEFT SIDE AND BUMPER IS LOOSE
9	GGW880EC	VW POLO VIVO 1.6 SEDAN	MM	6	183 350	Uneconomic to maintain due to age	GOOD	3 MAGS, 1 RIM & DENTS - FRONT SIDE CHIPS
10	GGW741EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	195 016	Uneconomic to maintain due to age	GOOD	DENTS - LEFT SIDE MINOR SCRATCHES
11	GGW897EC	VW POLO VIVO 1.6 SEDAN	MM	6	209 655	Uneconomic to maintain due to age	FAIR	FRONT LOGO MISSING, 3 MAGS & 1 RIM
12	GGW898EC	VW POLO VIVO 1.6 SEDAN	MM	6	188 683	Uneconomic to maintain due to age	GOOD	BROKEN BUMPER FRONT SIDE
13	GGW899EC	VW POLO VIVO 1.6 SEDAN	MM	6	209 255	Uneconomic to maintain due to age	GOOD	WHEEL CAPS - MAG
14	GGW736EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	129 313	Uneconomic to maintain due to age	GOOD	RADIO NOT WORKING, DENTS - RIGHT SIDE SCRATCHES & NO SPARE KEY
15	GGW867EC	VW POLO VIVO 1.6 SEDAN	MM	6	179 713	Uneconomic to maintain due to age	GOOD	DENT ON FRONT AND RIGHT SIDE
16	GGW734EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	168 225	Uneconomic to maintain due to age	GOOD	NO TRIANGLE, DENTS LEFT SIDE - SCRATCHES & CHIPS ON LOAD BODY, REAR DOOR, MIRROR FENDER, DENTS - RIGHT SIDE SCRATCHES ON FENDER, BUMPER, DOORS, CHIPS & LOAD BODY; DENTS - FRONT SIDE CRACKED BUMPER, SMALL SCRATCHES ON BUMPER, BONNET + CHIP ON WINDSCREEN, NO TOW BAR, SCRATCHES ON TAIL GATE AND FRONT BUMPER LOOSE & CRACKED
17	GS555EC	VW AMAROK 2.0 BAKKIE	MM	6	123 716	Uneconomic to maintain due to age	GOOD	DENTS - RIGHT SIDE SMALL SCRATCHES AT THE BASE RIGHT SIDE
18	GGW735EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	189 367	Uneconomic to maintain due to age	GOOD	NO JACK, WHEELSPANNER, DENTS - LEFT SIDE AT THE BACK AND BUMPER
19	GGY735EC	NISSAN NP300 2.4 HR DOUBLE CAB	MM	5	109 531	Uneconomic to maintain to repair	FAIR	NO JACK, NO TRIANGLE, SCRATCHES ON LEFT FENDER & CRACK ON MILD FLIP
20	GGW730EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	159 148	Uneconomic to maintain due to age	GOOD	NO JACK, SPAREWHEEL, WHEEL SPANNER, TRIANGLE & RADIO
21	GGW866EC	VW POLO VIVO 1.6 SEDAN	MM	6	201 829	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
22	GGW729EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	130 623	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
23	GGW904EC	VW POLO VIVO 1.6 SEDAN	MM	6	260 996	Uneconomic to maintain due to age	FAIR	NO JACK, NO WHEEL SPANNER, NO TRIANGLE, FRONT BUMPER BROKEN AND RUST ON BONNET
24	GGW321EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	197 049	Uneconomic to maintain due to age	FAIR	NO JACK AND DENT ON LEFT REAR DOOR
25	GGW902EC	VW POLO VIVO 1.6 SEDAN	MM	6	160 428	Uneconomic to maintain due to age	GOOD	NO SPEAR KEY & NO DEFECTS DETECTED
26	GGW324EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	124 666	Uneconomic to maintain due to age	FAIR	BUMPER IS LOOSE
27	GGW738EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	173 453	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
28	GGW791EC	NISSAN HARDBODY 2.0 LWB PETROL	MM	15	173 369	Uneconomic to maintain due to age	FAIR	NO JACK, SPAREWHEEL, WHEEL SPANNER, RADIO, SCRATCHES LEFT SIDE & SCRATCHES REAR SIDE
29	GGW865EC	VW POLO VIVO 1.6 SEDAN	MM	6	199 803	Uneconomic to maintain due to age	FAIR	FRONT BUMPER DAMAGED
30	GGW877EC	VW POLO VIVO 1.6 SEDAN	MM	6	231 015	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
31	GGW890EC	VW POLO VIVO 1.6 SEDAN	MM	6	231 635	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
32	GGW894EC	VW POLO VIVO 1.6 SEDAN	MM	6	204 297	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
33	GGW792EC	NISSAN HARDBODY 2.0 LWB PETROL	MM	15	159 594	Uneconomic to maintain due to age	FAIR	NO JACK, SPAREWHEEL, WHEEL SPANNER, RADIO, SCRATCHES LEFT SIDE, SCRATCHES RIGHT SIDE, CHIPS & SCRATCHES FRONT SIDE & SCRATCHES & DENTS REAR SIDE
34	GS5503EC	MERCEDEZ BENZ SPRINTER (PANEL VAN)	MM	19	109 478	Uneconomic to maintain due to age	FAIR	NO JACK, SPAREWHEEL; DENTS - LEFT & RIGHT SIDE, DENTS & SCRATCHES, SCRATCHES FRONT SIDE, SCRATCHES & DENTS REAR SIDE
35	GS551EC	VW AMAROK 2.0 BAKKIE	MM	7	125 633	Uneconomic to maintain due to age	GOOD	NO SPAREWHEEL, TRIANGLE, RADIO, SMALL DENT ON THE LEFT FENDER, SCRATCHES & SMALL DENT ON TH RIGHT FENDER & SCRATCHES FRONT SIDE
36	GS5520EC	VW POLO VIVO 1.4 SEDAN	MM	9	104 219	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
37	GGW869EC	VW POLO VIVO 1.6 SEDAN	MM	6	251 970	Uneconomic to maintain due to age	GOOD	WHEEL CAPS - ONE FRONT
38	GGW881EC	VW POLO VIVO 1.6 SEDAN	MM	6	261 644	Uneconomic to maintain due to age	GOOD	WHEEL CAPS - ONE MISSING
39	GGW728EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	179 237	Uneconomic to maintain due to age	GOOD	SMALL SCRATCH FRONT SIDE & ROLLER BAR BROKEN
40	GGW888EC	VW POLO VIVO 1.6 SEDAN	MM	6	381 473	Uneconomic to maintain due to age	FAIR	SCRATCHES & CHIPS ON REAR PANEL, DOORS, MIRROR, FENDER & PILL OFF ON BUMPER, SCRATCHES ON FENDER, MIRROR BROKEN, CHIPS ON DOOR & REAR PANEL, BUMPER BROKEN DUE TO ACCIDENT, CHIPS & SCRATCHES ON BUMPER & BONNET, NO BADGE ON GRILL AND WINDSCREEN BROKEN, FRONT INDICATOR NOT WORKING, NO PARKLIGHT ON RIGHT FRONT & NO DEEM ON FRONT LEFT AND WHEEL CAPS IT HAS MAGS
41	GGW868EC	VW POLO VIVO 1.6 SEDAN	MM	6	431 668	Uneconomic to maintain due to age	GOOD	FRONT BUMPER LOOSE & NOO SPARE KEY
42	GGX992EC	NISSAN HARDBODY NP300 D/CAB DIESEL	MM	7	132 339	Uneconomic to maintain due to age	GOOD	DENTS - LEFT SIDE SCRATCHES REAR FENDER
43	GGW901EC	VW POLO VIVO 1.6 SEDAN	MM	6	153 136	Uneconomic to maintain due to age	GOOD	NO JACK, NO SPAREWHEEL, NO WHEEL SPANNER & NO RADIO
44	GGW879EC	VW POLO VIVO 1.6 SEDAN	MM	6	145 053	Uneconomic to maintain due to age	GOOD	NO TRIANGLE & NO VW SYMBOL OR BADGE

45	GG5519EC	VW POLO VIVO 1.6 SEDAN	MM	9	113 613	Uneconomic to maintain due to age	GOOD	SCRATCH RIGHT SIDE
58	GG5499EC	CITI GOLF VW	MM	15		Uneconomic to maintain due to age	POOR	Uneconomic to maintain due to age and repairs
46	GGW875EC	VW POLO VIVO 1.6 SEDAN	MM	6	203 771	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
47	GGW889EC	VW POLO VIVO 1.6 SEDAN	MM	6	171 464	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
48	GGW883EC	VW POLO VIVO 1.6 SEDAN	MM	6	158 013	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
49	GGW893EC	VW POLO VIVO 1.6 SEDAN	MM	6	155 440	Uneconomic to maintain due to age	GOOD	NO SPEAR KEY & DRILLER BROKEN
50	GGW386EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	104 119	Uneconomic to maintain due to age	FAIR	NO JACK, SPAREWHEEL, WHEEL SPANNER, TRIANGLE, RADIO & DENTS - FRONT SIDE BUMPER SCRATCHED
51	GG5554EC	VW AMAROK 2.0 BAKKIE	MM	7	144 745	Uneconomic to maintain due to age	FAIR	SCRATCHES LEFT & RIGHT SIDE
52	GGW903EC	VW POLO VIVO 1.6 SEDAN	MM	6	267 951	Uneconomic to maintain due to age	GOOD	DENTS - LEFT SIDE , FENDER , DOOR, BUMPER ;DENTS FRONT SIDE GRILL BROKEN CHIPS & DENT REAR SIDE -BUMPER
53	GGW315EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	190 913	Uneconomic to maintain due to age	GOOD	NO JACK, SPAREWHEEL, WHEEL SPANNER, TRIANGLE, RADIO & DENTS - LEFT SIDE FENDER DAMAGED & THE LEFT DOOR
54	GGW900EC	VW POLO VIVO 1.6 SEDAN	MM	6	188 453	Uneconomic to maintain due to age	FAIR	SCRATCH REAR SIDE & BROKEN BUMPER ON FRONT & RIGHT SIDE
55	GGW882EC	VW POLO VIVO 1.6 SEDAN	MM	6	190 110	Uneconomic to maintain due to age	GOOD	MAGS & NO SPARE KEY
56	GGW885EC	VW POLO VIVO 1.6 SEDAN	MM	6	179 583	Uneconomic to maintain due to age	GOOD	DENTS - FRONT SIDE SCRATCHES & NO SPARE KEY
57	GGW733EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	148 215	Uneconomic to maintain due to age	FAIR	NO JACK, SPAREWHEEL, WHEEL SPANNER, TRIANGLE, RADIO, ROLLER BAR;DENTS - LEFT SIDE SCRATCHES AND DENTS - FRONT SIDE LOOSE BUMPER
58	GGW323EC	NISSAN HARDBODY 2.4 DOUBLE CAB 4X4	MM	6	174 888	Uneconomic to maintain due to age	FAIR	NO JACK, SPAREWHEEL, WHEEL SPANNER, TRIANGLE & DENTS - FRONT SIDE BUMPER DIPS OFF AND BONNET HAIL STORM DAMAGE
59	GGW876EC	VW POLO VIVO 1.6 SEDAN	MM	6	211 179	Uneconomic to maintain due to age	GOOD	REAR SIDE - BUMPER LOOSE AT THE BOTTOM
60	GGW886EC	VW POLO VIVO 1.6 SEDAN	MM	6	288 803	Uneconomic to maintain due to age	GOOD	NO JACK, NO TOWING SCREW, DENTS - FRONT SIDE BROKEN DRILL & DENTS - REAR SIDE SCRATCHES
61	GGW887EC	VW POLO VIVO 1.6 SEDAN	MM	6	268 191	Uneconomic to maintain due to age	GOOD	NO DEFECTS DETECTED
62	GG5532EC	HARDBODY 2.4 HI-RIDER DOUBLE CAB PETROL	MM	6	255 960	Uneconomic to maintain due to age	FAIR	NO DEFECTS DETECTED
63	GGW872EC	VW POLO VIVO 1.6 SEDAN	MM	6	200 170	Uneconomic to maintain due to age	GOOD	SCRATCHES ON REAR PANEL& BUMPER, SMALL SCRATCHES & CHEAPS ON BUMPER + BONNET + WINDSCREENS HAS CHEAPS, SMALL SCRATCHES & CHEAPSON BUMPER & BOOT AND NO WHEEL CAPS IT HAS MAGS
64	GG5521EC	VW POLO VIVO 1.6 SEDAN	MM	9	140 198	Uneconomic to maintain due to age	FAIR	SMALL SCRATCHES LEFT & RIGHT SIDE, REAR PANEL CHEAP, FRONT DOOR RUBBER NOT RIGHT, DENT & SCRATCHESON REAR DOOR & REAR PANEL, BUMPER GRILL LEFT CORNER OUT, SMALL SCRATCHES & CHEAPS ON BONNET, BUMPER & NO BADGE ON GRILL, SMALL SCRATCHES ON BUMPER AND IT IS NOT LOCKING